



Notes:

1. General dimensions and floor plan review was completed for the first floor.
2. Any future Tenant fit-up plan will require spot verification of tight areas and column intersections.